


FIG. 2A



٠,

FIG. 2B





FIG. 3



٠,

> <- 256 Sample > 16 Sample

FIG. 4A




FIG. 4B




FIG. 4C




FIG. 5




FIG. 6




FIG. 7




FIG. 8

```
C1 = A1 \times B9 + A2 \times B8 + A3 \times B7 + A4 \times B6 + A5 \times B5 + A6 \times B4 + A7 \times B3 + A8 \times B2
                 +A9×Bi
 C2 = A1 \times B10 + A2 \times B9 + A3 \times B8 + A4 \times B7 + A5 \times B6 + A6 \times B5 + A7 \times B4 + A8 \times B3
                 +A9 ×B2 +A10×B1
 C3 = A1 \times B11 + A2 \times B10 + A3 \times B9 + A4 \times B8 + A5 \times B7 + A6 \times B6 + A7 \times B5 + A8 \times B4
                 +A9×B3 +A10×B2 +A11×B1
A1×B12+A2×B11 +A3×B10 +A4×B9 +A5×B8 +A6×B7 +A7×B6 +A8×B5
                 +A9×B4 +A10×B3 +A11 ×B2 +A12×B1
                 A1×B/3+A2×B/2 +A3×B/1 +A4×B/0 +A5×B9 +A6×B8 +A7×B7 +A8×B6
+A9×B5 +A10×B4 +A11×B3 +A12×B2 +A13×B/
C6 = A1 \times B14 + A2 \times B13 + A3 \times B12 + A4 \times B11 + A5 \times B10 + A6 \times B9 + A7 \times B8 + A8 \times B7 + A9 \times B6 + A10 \times B5 + A11 \times B4 + A12 \times B3 + A13 \times B2 + A14 \times B1
THY XBO +A(U XBC) THI Y XBO +A(12 XBC) +A(15 XBC) +A(14 XBC)

C7 = A1 XBI5 +A2 XBI4 +A3 XBI3 +A4 XBI2 +A5 XBI1 +A6 XBI0 +A7 XBO +A8 XBS +A(14 XBC) +A(15 X
                 +A11 ×B8+A12×B7 +A13×B6 +A14×B5 +A15×B4 +A16×B3
C11 = A4×B16+A5×B15+A6×B14+A7×B13+A8×B12+A9×B11+A10×B10+A11×B9
+A12×B8+A13×B7+A14×B6+A15×B5+A16×B4
C12 = A5 \times B16 + A6 \times B15 + A7 \times B14 + A8 \times B13 + A9 \times B12 + A10 \times B11 + A11 \times B10 + A12 \times B9
+A/3×B8+A/4×B7 +A/5×B6 +A/16×B5

C/3= A6×B/6+A7×B/5 +A8×B/4 +A9×B/3 +A/0×B/2+A/17×B/11+A/2×B/0+A/3×B9

+A/4×B8+A/5×B7 +A/6×B6
CI4 = A7 \times B16 + A8 \times B15 + A9 \times B14 + A10 \times B13 + A11 \times B12 + A12 \times B11 + A13 \times B10 + A14 \times B9
                +A15×B8+A16×B7
CIS= A8×BI6+A9×BI5+A10×BI4+A11×BI3+A12×B12+A13×B11+A14×B10+A15×B9
                 +A16×B8
C16= A9×B16+A10×B15+A11×B14+A12×B13+A13×B12+A14×B11+A15×B10+A16×B9
```

FIG. 9




FIG. 10 °




FIG. 11

PRIOR ART




FIG. 12

PRIOR ART




FIG. 13

PRIOR ART




FIG. 14

PRIOR ART




FIG. 15




FIG. 16




FIG. 17



